


Triplet Tap Hole Can't Be Punctured

CODE	A	B	C
91351	350	280	115



CODE	D	E	n
91351	140	795	220

91351